Queensbury Laboratory Accredited in accordance with NELAC

Queensbury Water Department 823 Corinth Rd Queensbury, N.Y. 12804-9725 (518) 793-8866 New York State Certification # 10565 EPA Lab Code # NY01262

Report of Bacteriological Examination

Date Collected: 10/15/2018

Date Tested: 10/15/2018

Collected By: Eric

Sample Point: Kitchen Faucet

Address of Sample: 53 South Main St., New Fire House, Salem, NY

Supplier: Salem Water Department

Fed Id: 5730106

Sample Number: 93238

Time Collected: 10:00 AM

Time Tested: 1:35 PM

Sample Age (hours)

3.58

Total Coliform (#/100ml): <1

Heterotrophic Plate Count (#/1ml):

E. Coli:

Field tested Free Chlorine: 1.21

Procedures Used:

Coliform, Total / E. coli (Qualitative) SM 18-22 9222A,B,C (-97)/40 CFR 141.

Standard Plate Count

SM18-22 9215B (-00)

At the time the sample was submitted, the sample MET the bacteriological requirements for a public water supply as set forth in Subpart 5-1.51 of the State Sanitary Code under Public Health Law, Section 225.

Sample Qualifier:

Laboratory Director or Designee